

VOLVO

04/2019 >> S60 III

S90 II 07/2016 >> 12/2020 V60 II 07/2018 >> 06/2022

V60 II Cross Country 03/2019 >> 06/2022 V90 II 07/2016 >> 12/2020

V90 Cross Country 01/2017 >> 12/2020 C40 Recharge 11/2021 >> 05/2024

EC40 06/2024 >> EX40 06/2024 >> XC40 03/2018 >>

XC40 Recharge 12/2020 >> 05/2024


XC40 Hybride 12/2020 >> XC60 II 07/2017 >> XC90 II 06/2015 >>

LYNK & CO

_{12/2020 >>} Part No: VL-048-07MU 01

Electric wiring kit for towbars / 7-pin / 12N / 12 Volt / ISO 1724









IMPORTANT!

This electric kit has to be installed by a professional workshop or a suitable qualified person.

The installation instructions must have been read and fully understood before the start of any installation. Please contact your wiring kit provider or the hotline shown in the footer

Make sure the vehicle is approved/homologated by the manufacturer to tow a trailer!

Also please check that there is a definite compatibility between this vehicle and the electric kit!

Following the installation of the electric kit, the fitting instructions should be kept together with the vehicle service document and vehicle handbook. The fitting instructions contain important information relating to the use and function of the towing kit as well as for any diagnostic or activation process, that might have to be repeated in the future (e.g. after the performance of a vehicle software update).

All warranty claims will be forfeited if the electric kit or components contained therein are used incorrectly or modified. If a towing socket adaptor has been used to connect to the trailer or bike rack, this must be removed from the trailer socket once the trailer or bike rack has been disconnected

If the trailer or bike rack is not equipped with a rear fog lamp, depending on the towing vehicle type, the correct function of the towing kit cannot be guaranteed. In such cases, a rear

This towing electric kit will not be covered under warranty if any technical or electrical modifications or software updates have been performed by the vehicle manufacturer after the initial commissioning of the kit. That applies especially to modifications or updates which may cause malfunctions in the trailer socket or any other part of the trailer electrical

Depending on the type of trailer module used in this electric kit, diagnostic interrogation with the vehicle's electrical system may be limited or will not function. The error memory inside the trailer module may not be able to be accessed by vehicle manufacturers diagnostic system.

Error logs relating to the trailer electrical equipment, that may be generated in the vehicle manufacturers diagnostic system as a result of a test procedure, may be due to the incorrect installation of the towing electric kit or the false activation of the trailer module.

We always recommend whenever possible, the following troubleshooting process:

- An analysis of the vehicle's error memory and possibly clearing of all faults before the start of the installation!
- Try disconnecting the trailer module from the towing harness and re-start the fault clearing process!
- → If in doubt, limit the time for troubleshooting to a max of 0,5 hours and call our Technical Support Team!

Please follow our instructions carefully and always test the towing electrics using a true lighting board or a specifically designed bulb tester. If an LED tester is used, ensure it is equipped with correct load resistors or malfunctions will occur!

This instruction is subject to changes and we reserve the right to make changes to design, colour etc.

All of the data and illustrations may not be an exact representation but the text contained in this instruction must be observed!


1/4

oo 3 Hardman Street Manchester M3 3AT

SALE: +44 (0) 1625 462281 TECHNICAL: +44 (0) 7440 202052 WEB: www.ecs-electronicsuk.co.uk

Email-sales: uksales@ecs-electronics.com Email-technical: ukts@ecs-electronics.com

Revision: 1 / 09.09.2024 VL-048-07MU




Optional




Consult your supplier.



1





Fitting Instructions




Download

from



www.ecs-electronicsuk.co.uk



Note: It may be necessary to check if this vehicle has a stored radio code before disconnecting the battery!



4

3/4

